

4.10 The major factors are: the reflection coefficient, τ_g , element tolerances, and element losses.